

VEHICLE INSPECTION REPORT

Inspected by: TEST PARTNER

Date:	03 Sep 2025
Vehicle:	Audi Q7 2020
VIN:	087179684785
Regional Specs:	GCC
Transmission:	automatic
Fuel:	Petrol

Estimated Fixing Cost	Estimated Market Value
AED5,000.00	AED65,000.00

Exterior

Component	Status
Front Left Door	Passed
Front Right Door	Passed
Rear Left Door	Passed
Rear Right Door	Passed
Left Fender	Passed
Right Fender	Passed
Left Quarter Panel	Passed
Right Quarter Panel	Passed
Front Bumper	Passed

Component	Status
Rear Bumper	Passed
Hood	Passed
Trunk	Passed
Roof	Passed
Left A Pillar	Passed
Right A Pillar	Passed
Left A To B Pillar Beading	Passed
Right A To B Pillar Beading	Passed
Right A To B Pillar	Passed
Left B Pillar	Passed
Left B Pillar Trim	Passed
Left B To C Pillar Beading	Passed
Right C Pillar Trim	Passed
Right B To C Pillar	Passed
Right B To C Pillar Beading	Passed
Left C Pillar	Passed
Left Running Board	Passed
Right Running Board	Passed
Sunroof Glass	Passed
Front Windshield	Passed
Rear Windshield	Passed
Chassis Condition	Passed
Apron	Passed

Component	Status
Boot Floor	Passed
Firewall Condition	Passed
Cowl Top	Passed
Head Light Support Condition	Passed
Left Hand Side Mirror	Passed
Left Side Mirror	Passed
Right Side Mirror	Passed
Left Front Alloy Rim	Passed
Left Rear Alloy Rim	Passed
Right Front Alloy Rim	Passed
Right Rear Alloy Rim	Passed
Spare Alloy Rim Condition	Passed
Wheel Cover	Passed
Antenna	Passed
Grill Condition	Passed
Monogram	Passed
Window Glass	Passed
Wiper	Passed
Rear Trunk Panel	Passed

Structural

No components found in this section.

Steering

Component	Status
Steering Wheel	Passed

Brakes

Component	Status
Parking Brake	Passed
Brake Master Cylinder	Passed
Brake Disc Pad	Passed
Brake Fluid	Passed

Suspension

Component	Status
Shock Absorbers	Passed

Interior

Component	Status
Dashboard Instrument Panel	Passed
Central Console	Passed
Glove Box	Passed
Steering Wheel	Passed
Sunvisor	Passed
Seat Upholstery	Passed

Component	Status
Manual Seat Movement	Passed
Seat Belts	Passed
Head Rest	Passed
Door Controls Trim	Passed
Grab Handle	Passed
Carpet	Passed
Headliner	Passed
Rear View Mirror	Passed
Toolkit	Passed

Engine

Component	Status
Engine Body	Passed
Engine Performance	Passed
Engine Oil Condition Level	Passed
Exhaust System	Passed
Radiator Condition	Passed
Radiator Coolant	Passed

Fuel

Component	Status
Fuel Tank	Passed

Transmission

Component	Status
Gear Shifting	Passed
Drive Axle	Passed
Transmission Fluid	Passed

Electrical

Component	Status
Master Key	Passed
Child Safety Locking	Passed
Instrument Panel	Passed
Airbags	Passed
Controls	Passed
Infotainment Display	Passed
Obd Connector	Passed
Music System	Passed
Sunroof	Passed
Camera	Passed
Headlight	Passed
Interior Lights	Passed
Tail Light Cluster	Passed
Daylight Running Lights	Passed
License Plate Light	Passed
Ac Cooling	Passed

Component	Status
Ac Switch	Passed
Ac System Leaks	Passed
Center Ac Vent	Passed
Front Right Ac Vent	Passed
Heater	Passed
Rear Blower Switch	Passed
Parking Sensors	Passed
Rear Defogger	Passed
Usb Charging Port	Passed
Power Manual Windows	Passed

Tyres

Component	Status
Lhs Front Tyre	Passed
Lhs Rear Tyre	Passed
Rhs Front Tyre	Passed
Rhs Rear Tyre	Passed
Spare Tyre	Passed
Lhs Front Tyre Life	Passed
Lhs Rear Tyre Life	Passed
Rhs Front Tyre Life	Passed
Rhs Rear Tyre Life	Passed
Spare Tyre Life	Passed