VEHICLE INSPECTION REPORT

Inspected by: SEA SANDS

Date: 03 Sep 2025

Vehicle: Mercedes-Benz GLE 350 2017

VIN: 4JGDXXXXXXX77

Regional Specs: American

Transmission: automatic

Fuel: Petrol

Estimated Fixing Cost	Estimated Market Value
AED3,000.00	AED30,000.00

Exterior

Component	Status
Front Left Door	Needs Fixing
Front Right Door	Needs Fixing
Rear Left Door	Passed
Rear Right Door	Passed
Left Fender	Passed
Right Fender	Passed
Left Quarter Panel	Passed
Right Quarter Panel	Needs Fixing
Front Bumper	Passed

Component	Status
Rear Bumper	Passed
Hood	Passed
Trunk	Passed
Roof	Passed
Left A Pillar	Needs Fixing
Right A Pillar	Needs Fixing
Left A To B Pillar Beading	Passed
Right A To B Pillar Beading	Passed
Right A To B Pillar	Needs Fixing
Left B Pillar	Passed
Left B Pillar Trim	Passed
Left B To C Pillar Beading	Passed
Right C Pillar Trim	Needs Fixing
Right B To C Pillar	Passed
Right B To C Pillar Beading	Needs Fixing
Left C Pillar	Needs Fixing
Left Running Board	Passed
Right Running Board	Needs Fixing
Sunroof Glass	Needs Fixing
Front Windshield	Needs Fixing
Rear Windshield	Needs Fixing
Chassis Condition	Needs Fixing
Apron	Passed

Component	Status
Boot Floor	Needs Fixing
Firewall Condition	Needs Fixing
Cowl Top	Needs Fixing
Head Light Support Condition	Passed
Left Hand Side Mirror	Needs Fixing
Left Side Mirror	Needs Fixing
Right Side Mirror	Needs Fixing
Left Front Alloy Rim	Needs Fixing
Left Rear Alloy Rim	Needs Fixing
Right Front Alloy Rim	Needs Fixing
Right Rear Alloy Rim	Needs Fixing
Spare Alloy Rim Condition	Needs Fixing
Wheel Cover	Needs Fixing
Antenna	Needs Fixing
Grill Condition	Needs Fixing
Monogram	Needs Fixing
Window Glass	Needs Fixing
Wiper	Needs Fixing
Rear Trunk Panel	Needs Fixing

Structural

No components found in this section.

Steering

Component	Status
Steering Wheel	Needs Fixing

Brakes

Component	Status
Parking Brake	Needs Fixing
Brake Master Cylinder	Needs Fixing
Brake Disc Pad	Needs Fixing
Brake Fluid	Needs Fixing

Suspension

Component	Status
Shock Absorbers	Needs Fixing

Interior

Component	Status
Dashboard Instrument Panel	Needs Fixing
Central Console	Needs Fixing
Glove Box	Needs Fixing
Steering Wheel	Needs Fixing
Sunvisor	Needs Fixing
Seat Upholstery	Needs Fixing

Component	Status
Manual Seat Movement	Needs Fixing
Seat Belts	Needs Fixing
Head Rest	Needs Fixing
Door Controls Trim	Needs Fixing
Grab Handle	Needs Fixing
Carpet	Needs Fixing
Headliner	Needs Fixing
Rear View Mirror	Needs Fixing
Toolkit	Needs Fixing

Engine

Component	Status
Engine Body	Needs Fixing
Engine Performance	Needs Fixing
Engine Oil Condition Level	Needs Fixing
Exhaust System	Needs Fixing
Radiator Condition	Needs Fixing
Radiator Coolant	Needs Fixing

Fuel

Component	Status
Fuel Tank	Needs Fixing

Transmission

Component	Status
Gear Shifting	Needs Fixing
Drive Axle	Needs Fixing
Transmission Fluid	Needs Fixing

Electrical

Component	Status
Master Key	Needs Fixing
Child Safety Locking	Needs Fixing
Instrument Panel	Needs Fixing
Airbags	Needs Fixing
Controls	Needs Fixing
Infotainment Display	Needs Fixing
Obd Connector	Needs Fixing
Music System	Needs Fixing
Sunroof	Needs Fixing
Camera	Needs Fixing
Headlight	Needs Fixing
Interior Lights	Needs Fixing
Tail Light Cluster	Needs Fixing
Daylight Running Lights	Needs Fixing
License Plate Light	Needs Fixing
Ac Cooling	Needs Fixing

Component	Status
Ac Switch	Needs Fixing
Ac System Leaks	Needs Fixing
Center Ac Vent	Needs Fixing
Front Right Ac Vent	Needs Fixing
Heater	Needs Fixing
Rear Blower Switch	Needs Fixing
Parking Sensors	Needs Fixing
Rear Defogger	Needs Fixing
Usb Charging Port	Needs Fixing
Power Manual Windows	Needs Fixing

Tyres

Component	Status
Lhs Front Tyre	Needs Fixing
Lhs Rear Tyre	Needs Fixing
Rhs Front Tyre	Needs Fixing
Rhs Rear Tyre	Needs Fixing
Spare Tyre	Needs Fixing
Lhs Front Tyre Life	Needs Fixing
Lhs Rear Tyre Life	Needs Fixing
Rhs Front Tyre Life	Needs Fixing
Rhs Rear Tyre Life	Needs Fixing
Spare Tyre Life	Needs Fixing